

**പതിമൂന്നാം കേരള നിയമസഭ
പതിനൊന്നാം സമ്മേളനം**

നക്ഷത്ര ചിഹ്നമിടാത്ത നിയമസഭാ
ചോദ്യം നമ്പർ: 8188

17.07.2014 ൽ മറുപടിക്ക്

വൈപ്പിൻ മണ്ഡലത്തിലെ കായലോരവാസികളുടെ സുരക്ഷ

ചോദ്യം

ശ്രീ. എസ്. ശർമ്മ

മറുപടി

ശ്രീ.പി.ജെ.ജോസഫ്
(ജലവിഭവകുപ്പ് മന്ത്രി)

വൈപ്പിൻ മണ്ഡലത്തിലെ കായലോരവാസികളുടെ സുരക്ഷയ്ക്കായി 661.55 ലക്ഷം രൂപ മുടക്കി പൂർത്തിയാക്കിയ പ്രവൃത്തികൾ ഏതൊക്കെ യെന്നും ഓരോ പ്രവൃത്തിയുടെയും പേര്, എസ്റ്റിമേറ്റ് തുക, നിർമ്മാണം പൂർത്തിയാക്കിയ തീയതി, ചെയിനേജ് എന്നിവ വിശദീകരിക്കുമോ?

വൈപ്പിൻമണ്ഡലത്തിലെ കായലോരവാസികളുടെ സുരക്ഷയ്ക്കായി വിനിയോഗിച്ച 805.65 ലക്ഷം രൂപയുടെ വിശദവിവരങ്ങൾ അനുബന്ധമായി ചേർത്തിരിക്കുന്നു. 11-06-2014-ാം തീയതിയിലെ നക്ഷത്രചിഹ്നമിടാത്ത 855-ാം നമ്പർ ചോദ്യത്തിനു മറുപടിയായി 805.65 ലക്ഷം രൂപയ്ക്കു പകരം 661.55 ലക്ഷം രൂപ എന്ന് തെറ്റായി സമർപ്പിച്ചത് മുഖ്യനിർണ്ണയിപ്പിശകിൽ സംഭവിച്ചതാണ് എന്ന് ചീഫ് എഞ്ചിനീയർ (ജലസേചനവും ഭരണവും) അറിയിച്ചിട്ടുണ്ട്.


 സെക്ഷൻ ഓഫീസർ

Promoted in WB

**DETAILS OF WORKS ARRANGED FOR THE SAFETY OF PEOPLE LIVING IN COASTAL
AREA OF VYPIN CONSTITUENCY**

(To be accompanied with answer to LA Qn No. 8188)

Sl. No	Name of Work	Estimate amount (Rs. In Lakhs)	Completion date
	ASE		
1	ASE - Reformation and raising of damaged seawall form Ch. 10910m to 10960m between CP Stone 4056 & 4057 at Edavanakad in Vypin Island	14.50	.5.2012
2	ASE - Reformation and raising of damaged seawall form Ch. 10963m to 11013m between CP Stone 4056 & 4058 at Edavanakad in Vypin Island	15.00	.8.2012
3	ASE - Replenishing back of seawall form Ch. 13990m to 14175m and Ch. 14463m to 14518m between CP Stone 4070 & 4074 near South of PH Centre at Nayarambalam in Vypin Island	12.90	99% Completed
4	ASE - Reformation and raising of damaged seawall form Ch. 4021m to 4106m (85m) between CP Stone 4032 & 4033 at Cherai in Vypin Island (Balance Work)	12.70	27.9.13
5	ASE - Reformation and raising of damaged sunken seawall form Ch. 2795m to 2842m (47m) between CP Stone 4028 & 4029 at Cherai in Vypin Island	15.00	18.2.14
6	ASE - Reformation and raising of damaged seawall form Ch. 11455m to 11505m between CP Stone 4058 & 4059 at Edavanakad in Vypin Island	15.00	31.3.14
7	ASE - Reformation and raising of damaged seawall from Ch. 11400m to 11445m between CP Stone 4057 & 4058 at Edavanakad in Vypin Island	15.00	29.3.14
8	ASE - Reformation and raising of damaged seawall from Ch. 11093m to 11133m between CP Stone 4057 & 4058 at Edavanakad in Vypin Island	15.00	25.3.14
9	ASE - Reformation and raising of damaged seawall from Ch. 10870m to 10910m between CP Stone 4056 & 4057 at Edavanakad in Vypin Island	15.00	25.3.14