

പതിനാലാം കേരള നിയമസഭ

പതിനാലാം സമ്മേളനം

നക്ഷത്രചിഹ്നമിടാത്ത ചോദ്യം നമ്പർ: 1796

05.02.2019-ലെ മറുപടിക്ക്

കെ.എസ്.ആർ.ടി.സി.ക്കുണ്ടായ നാശനഷ്ടം

ചോദ്യം

ശ്രീ.രാജു എബ്രഹാം

മറുപടി

ശ്രീ. എ.കെ. ശശീന്ദ്രൻ

(ഗതാഗത വകുപ്പു മന്ത്രി)

<p>(എ) കഴിഞ്ഞ നവംബർ മാസം മുതൽ വിവിധ സമരങ്ങളുടെ ഭാഗമായി കെ.എസ്.ആർ.ടി.സി. ബസുകൾക്കും ബസ് സ്റ്റേഷനുകൾക്കും നേരെയുള്ള ആക്രമങ്ങളിൽ എത്ര രൂപയുടെ നാശനഷ്ടമാണ് കെ.എസ്.ആർ.ടി.സി.ക്ക് ഉണ്ടായതെന്ന് കണക്കാക്കിയിട്ടുണ്ടോ; വിശദാംശങ്ങൾ ലഭ്യമാക്കാമോ;</p>	<p>(എ) വിവിധ സമരങ്ങളുടെ ഭാഗമായി കെ.എസ്.ആർ.ടി.സി. ബസുകൾക്കും ബസ് സ്റ്റേഷനുകൾക്കും നേരെയുള്ള ആക്രമണങ്ങളോടനുബന്ധിച്ച് കോർപ്പറേഷന്റെ 102 ബസ്സുകൾക്ക് നേരെ ആക്രമണം ഉണ്ടാകുകയും കോർപ്പറേഷന് 3,35,00,000/- രൂപയുടെ നഷ്ടം ഉണ്ടാവുകയും ചെയ്തിട്ടുണ്ട്. കേടുപാടുകൾ സംബന്ധിച്ച വിവരം അനുബന്ധം ആയി ചേർക്കുന്നു.</p>
<p>(ബി) കെ.എസ്.ആർ.ടി.സി.ക്ക് ഉണ്ടായ നാശനഷ്ടം ഈടാക്കുന്നതിന് നടപടി സ്വീകരിച്ചിട്ടുണ്ടോ; വിശദാംശങ്ങൾ വ്യക്തമാക്കാമോ?</p>	<p>(ബി) ടി തുക ഈടാക്കുന്നത് സംബന്ധിച്ച് സ്റ്റേറ്റ് പോലീസ് ചീഫ് & ഡയറക്ടർ ജനറൽ ഓഫ് പോലീസിന് 10/01/2019-ൽ LA1/34544/18/WP(C) നമ്പർ പ്രകാരം കെ.എസ്.ആർ.ടി.സി. കത്ത് നൽകിയിട്ടുണ്ട്.</p>

സെക്ഷൻ ഓഫീസർ

Coronavirus

DAMAGE DUE TO PUBLIC AGITATION ON-2/1/2019				
SL NO.	DISTRICT	Bus no	Depot	Damages sustained
1	ALP	RSM539	ALP	Windshield glass
2	ALP	RSE128	CGNR	Windshield glass and Rear emergency glass
3	ALP	RPC726	CTL	Windshield glass
4	ALP	RPE53	KYLM	Windshield glass
5	EKM	RSK399	PRR	Windshield glass
6	EKM	RSC819	PVM	Windshield glass and Rear emergency glass
7	IDK	RSC891	KTP	Rear Emergency glass
8	IDK	RAC35	KTP	Rear Emergency glass & Tail lamps
9	KGD	RPK485	KHG	Windshield glass
10	KGD	ATC236	KHG	Windshield glass
11	KGD	RSC503	KSGD	Windshield glass
12	KGD	RSC427	KSGD	Windshield glass
13	KGD	RNK366	KSGD	Windshield glass
14	KKD	JN345	KKD	Rear Emergency glass, side glass-1
15	KKD	RSC856	KKD	Rear Emergency glass
16	KKD	ATK48	TDY	Windshield glass
17	KKD	RNC667	TSY	Rear Emergency glass
18	KLM	RSC959	CTNR	Windshield glass
19	KLM	RPE132	KLM	Windshield glass and door glass
20	KLM	RAM889	KLM	Windshield glass
21	KLM	RPA48	KLM	Windshield glass
22	KLM	RNC66	KLM	Windshield glass
23	KLM	RRC287	KLM	Windshield glass
24	KLM	RSC888	KLM	Windshield glass
25	KLM	RNC69	KLM	Head light
26	KLM	RNE423	KPZA	Windshield glass and door glass
27	KLM	RAC806	KPZA	Windshield glass and Rear emergency glass
28	KLM	RSC674	KPZA	Windshield glass
29	KLM	RPA706	KTR	Windshield glass and Rear emergency glass
30	KLM	RRC707	KTR	Windshield glass and Rear emergency glass
31	KLM	RPA356	KTR	Head light
32	KLM	RNC196	KTR	Head light
33	KLM	RNE600	KTR	Windshield glass
34	KLM	RPK380	KTR	Windshield glass
35	KLM	RSC973	KTR	Head light
36	KLM	RNK489	KTR	Rear Emergency glass
37	KLM	RSC705	PLR	Windshield glass
38	KLM	ATM108	PLR	Head light
39	KNR	RSC518	PNR	Door glass
40	KNR	RSK243	PNR	Windshield glass
41	KNR	RSK577	TLY	Windshield glass
42	KTM	ATC95	CHRY	Rear Emergency glass
43	KTM	RPK126	EMLY	Windshield glass
44	KTM	RSC977	ETPA	Windshield glass
45	KTM	ATC256	PALA	Driver door glass
46	MPM	RSC147	MLP	Windshield glass
47	MPM	RRK634	MPM	Windshield glass
48	MPM	RSA54	MPM	Rear designation glass & quarter glasses
49	MPM	RRQ933	NBR	Windshield glass

50	MPM	RRC828	NBR	Head light
51	MPM	RNM907	PNI	Rear designation glass & quarter glasses
52	PLKD	RSK75	CTR	Windshield glass
53	PLKD	RSK75	CTR	Windshield glass
54	PLKD	RPM734	MKD	Windshield glass
55	PLKD	RPC938	PLK	Windshield glass
56	PLKD	RSE617	PLK	Windshield glass
57	PLKD	RSC205	VDCY	Windshield glass
58	PTA	FAE968	ADR	Windshield glass
59	PTA	RNK551	ADR	Windshield glass
60	PTA	AT408	PAMBA	Windshield glass
61	PTA	RAK894	PTA	Windshield glass
62	PTA	RPC25	PTA	Rear Emergency glass
63	PTA	RFC895	PTA	Windshield glass
64	PTA	RAK894	PTA	Windshield glass
65	PTA	RSC386	RNI	Rear Emergency glass
66	PTA	RAE271	RNI	Windshield glass
67	PTA	RPA11	TVLA	Windshield glass
68	TSR	RSC592	GVR	Driver door glass
69	TSR	FAM289	GVR	Front right corner glass
70	TSR	ATC151	KDLR	Windshield glass
71	TSR	ATC154	KDLR	Windshield glass
72	TSR	RSO787	PKD	Windshield glass
73	TSR	ATK306	TSR	Windshield glass
74	TVM	RF716	CITY	Windshield glass
75	TVM	RAC94	CITY	Windshield glass
76	TVM	RAE306	KTDA	Windshield glass
77	TVM	RFA951	NTA	Windshield glass
78	TVM	RFA273	NTA	Windshield glass
79	TVM	RAK62	NTA	Windshield glass
80	TVM	RNK698	NTA	Quarter glass
81	TVM	RSM660	NTA	Windshield glass
82	TVM	RAK684	PSLA	Windshield glass
83	TVM	RFB947	PSLA	Windshield glass
84	TVM	RNC815	PSLA	Windshield glass
85	TVM	RAC81	PSLA	Windshield glass
86	TVM	RFA275	RELA	Windshield glass
87	TVM	RPC231	RVR	Windshield glass
88	TVM	RPC505	RVR	Windshield glass
89	TVM	RNK447	RVR	Windshield glass
90	TVM	RFC619	RVR	Windshield glass
91	TVM	RAM680	RVR	Quarter glass
92	TVM	RPC108	TVM	Rear Emergency glass
93	TVM	RPE51	TVM	Front body damage
94	TVM	ATM109	TVM CL	Windshield glass
95	TVM	ATA178	TVMCL	Windshield glass
96	TVM	RAK969	VKB	Rear Emergency glass
97	TVM	RRA316	VKB	Rear Emergency glass
98	TVM	RSM28	VZM	Windshield glass
99	WYD	RSC901	MDY	Windshield glass
100	WYD	RSC96	MDY	Windshield glass

101	WYD	RNK82	MDY	Windshield glass
102	WYD	RPC56	SBY	Windshield glass

<u>District</u>	<u>No. of Buses</u>
Alapuzha	- 4
Emmakulam	- 2
Idukki	- 2
Kasaragod	- 5
Kozhikkod	- 4
Kollam	- 21
Kannur	- 3
Kottayam	- 4
Malappuram	- 6
Palakkad	- 6
Palakkad	- 10
Thiruvananthapuram	- 6
Thiruvananthapuram	- 25
Wayanad	- 4
	<hr/>
	102
	<hr/>



AMRITHA BISHNU